





**HELLO RE**  
Upholstery fabrics


 **svensson**




3062



3125



3326



3363



3544




3733




4271



4362



4443



4452



4461



4534



4644



4845




5041




5345



5672



5744



5931



6144

## HELLO RE

### Upholstery fabrics

**Breite:** 140 cm  
**Gewicht:** 280 G/M<sup>2</sup>  
**Material:** Recycled Trevira CS 100%  
**Einlaufen:** 2 %

**Color fastness:**  
*Against dry rubbing according to EN ISO 105-X12:*  
 - ≥ 4 (Scale 1-5)  
*Gegen Licht nach EN ISO 105-B02*  
 - ≥ 5-7 (Skala 1-8)  
*Against wet rubbing according to EN ISO 105-X12:*  
 - ≥ 3-4 (Scale 1-5)

**Scheuerfestigkeit:**  
*Martindale (Nach: EN ISO 12947-2):*  
 - 50000 Touren

**Schwerentflammbarkeit:**  
 - EN 1021-1&2 - DIN 4102-1  
 B1- BS 5852 Crib 5- EN 13501-1;  
 B-s1, d0- NFP 92-503-507 M1- IMO  
*FTP Code 2010:*  
 - DIN 4102-1 B1  
 - BS 5852 Crib 5  
 - EN 13501-1; B-s1, d0  
 - NFP 92-503-507 M1  
 - IMO FTP Code 2010: Part 8

#### Wartungsanweisungen:



#### For further information:

Svensson  
 511 82 Kinna, Sweden

T: +46 320 20 92 00  
 F: +46 320 21 10 10  
 E: info@ludvigsvensson.com





6442



6453



6530



6540



6570




6621



6631




6634



6662



6740




6742




6760




6943



8200




8300




8400



8500



8550



8700



8900

## HELLO RE

### Upholstery fabrics

**Breite:** 140 cm

**Gewicht:** 280 G/M<sup>2</sup>

**Material:** Recycled Trevira CS 100%

**Einlaufen:** 2 %

**Color fastness:**

Against dry rubbing according to

EN ISO 105-X12:

- ≥ 4 (Scale 1-5)

Gegen Licht nach EN ISO 105-B02

- ≥ 5-7 (Skala 1-8)

Against wet rubbing according to

EN ISO 105-X12:

- ≥ 3-4 (Scale 1-5)

**Scheuerfestigkeit:**

Martindale (Nach: EN ISO 12947-2):

- 50000 Touren

**Schwerentflammbarkeit:**

- EN 1021-1&2 - DIN 4102-1

B1- BS 5852 Crib 5- EN 13501-1;

B-s1, d0- NFP 92-503-507 M1- IMO

FTP Code 2010:

- DIN 4102-1 B1

- BS 5852 Crib 5

- EN 13501-1; B-s1, d0

- NFP 92-503-507 M1

- IMO FTP Code 2010: Part 8

**Wartungsanweisungen:**



**For further information:**

Svensson  
511 82 Kinna, Sweden

T: +46 320 20 92 00

F: +46 320 21 10 10

E: info@ludvigsvensson.com

